

BEG/INT/ADV METAL SCULPTURE

INSTRUCTOR: T STONE

Welcome to Metal Arts! We'll be working with heavy industrial equipment, so please show up to the first class with the required items if you are new!

Our dress code requires **LONG PANTS** or **JEANS** as well as a **LONG SLEEVE SHIRT** (**NO BUTTON UPS**).

REQUIRED



WELDING HELMET

Please bring your own self-darkening welding helmet. If you're a beginner, please feel free to purchase a lesser-cost version from Harbor Freight.



HEARING PROTECTION

Bring a decent set of hearing protection as the welding area tends to be loud.



SAFETY GLASSES

You will need a clear plastic pair for grinding and a dark pair for cutting. If you wear prescription glasses, make sure these safety glasses will fit comfortably over the top of them.



FOOTWEAR

Leather workboots are preferred. **NO TENNIS SHOES OR OPEN TOE SHOES.**



LINESMAN PLIERS

Please purchase linesman pliers. Make sure to get a reputable brand as these tend to last longest.

LEATHER GLOVES

Please pick up a pair of leather work gloves.

OPTIONAL



LEATHER BIB

This item will keep your clothing from wearing out too quickly. We suggest a crossback design rather than the thru-neck design seen here.



GRINDER

A decent grinder can be expensive. We suggest you start your class before purchasing as these items are an investment.